

# MATERIAL SAFETY DATA SHEET

## SECTION I - MANUFACTURER'S INFORMATION

<b>MANUFACTURER'S NAME</b>	WOODSTREAM CORPORATION  69 NORTH LOCUST STREET  LITITZ, PA 17543
<b>EMERGENCY TELEPHONE NUMBER</b>	800-424-9300
<b>TELEPHONE NUMBER FOR INFORMATION</b>	717-626-2125

## SECTION II - HAZARDOUS INGREDIENTS / IDENTITY INFORMATION

### **M327 RPT Roach Pheromone Trap** - NO CAS NUMBER

THIS PRODUCT WOULD NOT BE CONSIDERED TOXIC AS DEFINED BY THE FEDERAL HAZARDOUS SUBSTANCE ACT OR THE U.S. DEPARTMENT OF TRANSPORTATION.

## SECTION III - PHYSICAL AND CHEMICAL CHARACTERISTICS

<b>BOILING POINT</b>	N/A
<b>VAPOR PRESSURE (mmHg)</b>	N/A
<b>VAPOR DENSITY (Air = 1)</b>	HEAVIER THAN AIR
<b>SPECIFIC GRAVITY (H<sub>2</sub>O = 1)</b>	0.875 (GLUE)
<b>MELTING POINT</b>	150°F (GLUE)
<b>EVAPORATION RATE (BUTYL ACETATE = 1)</b>	N/A
<b>SOLUBILITY IN WATER</b>	N/A
<b>APPEARANCE</b>	CLEAR TO LIGHT YELLOW SOLID (GLUE)  WHITE/YELLOW WOOD MATERIAL  (PHEROMONE CARRIER) CARDBOARD  WITH CLEAR PLASTIC
<b>ODOR</b>	INSECT SPECIFIC NATURAL AGGREGATION PHEROMONE

## SECTION IV - FIRE AND EXPLOSION HAZARD DATA

<b>FLASH POINT (METHOD USED)</b>	400°F
<b>FLAMMABLE LIMITS</b>	N/A
<b>LEL</b>	N/A
<b>UEL</b>	N/A
<b>EXTINGUISHING MEDIA</b>	CO <sub>2</sub> CHEMICAL FOAM

<b>SPECIAL FIRE-FIGHTING PROCEDURES</b>	TO PREVENT SPLATTERING AND SPREADING OF FIRE, DO NOT POUR WATER ON MOLTEN MATERIAL.
<b>UNUSUAL FIRE AND EXPLOSION HAZARDS</b>	NONE
<b>SECTION V - REACTIVITY DATA</b>	
<b>STABILITY</b>	STABLE
<b>CONDITIONS TO AVOID</b>	N/A
<b>INCOMPATIBILITY</b>	N/A
<b>(MATERIALS TO AVOID)</b>	
<b>HAZARDOUS DECOMPOSITION OR BY</b>	N/A
<b>PRODUCTS</b>	
<b>HAZARDOUS POLYMERIZATION</b>	WILL NOT OCCUR

<b>SECTION VI - HEALTH HAZARD DATA</b>	
<b>ROUTES OF ENTRY:</b>	
<b>INHALATION?</b>	NO
<b>SKIN?</b>	NO
<b>INGESTION?</b>	NO
<b>HEALTH HAZARDS (ACUTE AND CHRONIC)</b>	NONE AT AMBIENT TEMPERATURES. PHEROMONE IS IN STERILIZED FORM.
<b>CARCINOGENICITY:</b>	
<b>NTP?</b>	N/A
<b>IARC MONOGRAPHS?</b>	N/A
<b>OSHA REGULATED?</b>	N/A
<b>SIGNS AND SYMPTOMS OF EXPOSURE</b>	MAY PRODUCE IRRITATING VAPORS IF BURNED.
<b>MEDICAL CONDITIONS GENERALLY AGGRAVATED BY EXPOSURE</b>	NONE KNOWN
<b>EMERGENCY AND FIRST AID PROCEDURES</b>	REMOVE TO FRESH AIR. IN THE EVENT OF BURNS CAUSED BY SKIN CONTACT WITH MOLTEN MATERIAL, TREAT USING THERMAL BURN PROCEDURES.

<b>SECTION VII - PRECAUTIONS FOR SAFE HANDLING AND USE</b>	
<b>STEPS TO BE TAKEN IN EVENT</b>	N/A
<b>MATERIAL IS RELEASED OR SPILLED</b>	
<b>WASTE DISPOSAL METHOD</b>	BURY WITH TRASH IN COMPLIANCE WITH LOCAL, STATE, AND FEDERAL REGULATIONS.
<b>PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING</b>	STORE IN A COOL, DRY PLACE. REMOVE GLUE FROM SKIN, ETC., WITH VEGETABLE OIL.
<b>SECTION VIII - CONTROL MEASURES</b>	
<b>RESPIRATORY PROTECTION (SPECIFY TYPE)</b>	N/A
<b>VENTILATION</b>	N/A
<b>LOCAL EXHAUST</b>	N/A
<b>MECHANICAL (GENERAL)</b>	N/A
<b>SPECIAL</b>	N/A
<b>OTHER</b>	N/A
<b>PROTECTIVE GLOVES</b>	N/A
<b>EYE PROTECTION</b>	N/A
<b>OTHER PROTECTIVE CLOTHING OR EQUIPMENT</b>	N/A
<b>WORK/HYGIENIC PRACTICES</b>	REMOVE FROM SKIN WITH VEGETABLE OIL OR MILD SOLVENT.

**Updated:** 8/06/01

**Replaces:** 02/09/01

**Contact:** Nathan P. Ehresman, Regulatory Affairs/Pesticides

[Close Window](#)